

☐ UNCLASSIFIED☐ INTERNAL
USE ONLY☐ CONFIDENTIAL☒ SECRET

ROUTING AND RECORD SHEET

14 MAR 1958

SUBJECT: (Optional)

CONFIDENTIAL

FROM:

OFFICE OF COMMUNICATIONS
ROOM 2022, BUILDING EYE

DATE

6 Mar 58

25X1

TO: (Officer designation, room number, and building)

DATE

RECEIVED

FORWARDED

OFFICER'S
INITIALS

COMMENTS (Number each comment to show from whom to whom. Draw a line across column after each comment.)

1.

OC-E

2.

3.

4.

5.

6.

7.

8.

9.

10.

11.

12.

13.

14.

15.

ACTION

SUSPENSE

28 March 1958

Info: OC Out
OC-P

SEB	SD	SA	AA
MSB	FS	EE	FE
IMB	EM	SM	TI
RDB	EP	MM	

ACTION

COPY DETACHED FOR OC
RECORDS CONTROL

DOC 10 REV DATE 3-12-60 BY 008632

ORIG COMP 5 OPI 3 TYPE C

ORIG CLASS 22 PAGES 2010 REV CLASS C

JUST 22 NEXT REV 2010 AUTH: HR 70-2

CONFIDENTIAL

FORM
1 DEC 56

610

USE PREVIOUS
EDITIONS☒ SECRET☐ CONFIDENTIAL☐ INTERNAL
USE ONLY☐ UNCLASSIFIED

P-10000

VIA _____
(Specify Air or Sea Pouch)DISPATCH NO. 58- 452

25X1

SECRET
CLASSIFICATION

TO : Chief, KUCLUB

DATE 6 March 1958FROM : Chief, CRH

25X1

SUBJECT: General—Engineering

Specific—Transmitter Adaptor TA-1

REF: ENG 57-1543

1. In checking the drawings, schematic, etc. furnished by your office for the procurement by of the TA-1, several questions arose:

25X1

a. Schematic Diagram. It is assumed that the male continental plug mates with the power receptacle. If so, the receiver antenna lead, connection F, becomes grounded, and the Rec lead from the transmit* receive switch terminates in the C pin of the power receptacle which mates with a blank pin in the power cable male plug. Also, the receiver ground connection, unmarked pin in the power cable plug, mates with blank pin G in the power receptacle.

Pin lettering in error

b. Parts List, page 15 of Handbook. Capacitor C9 refers to DWG No. 2514-54 which is a Tank Coil.

C9 is being drawn

c. Drawing No. 1. Hinge blocks refer to drawing 14, which is a bar, switch. Parts labeled 2045-416 and 2045-258 are not shown on any drawing furnished with the reference.

should be #14 instead of #14

d. Drawing No. 36. Same comments as for drawing #1.

same

e. Drawing No. 4. This is probably the hinge block required by the assemblies shown on drawings #1 and #36. If so, the quantity should be 4 instead of 2.

2 for new case 2 for assembly case

f. Key. An assembly drawing of the built-in key would be helpful.

OK - key is being drawn

g. Figure 3, page 20, Handbook. This shows a fabric bag with the accessories, but not the accessory case. The case should be shown in the picture, and if the bag is desired, specifications should be furnished.

*by telephone 2 for assembly case***SECRET**
CLASSIFICATION**CONFIDENTIAL**

ORIGINAL RECEIVED COPY

SECRET

6 March 1958

- 2 -

58- 452

25X1

h. There is no drawing of the Telex Jack for the external key. The Telex Jack may not be readily identified by the prospective bidders.

2. It is requested that casting be approved as an alternate method of producing the case, accessory. This may better suit local methods.

3. Please furnish soonest corrected drawings, etc. to eliminate the discrepancies listed in paragraph 1 and to provide missing information.

FOR THE CHIEF,

25X1

25X1

EGV:mfw (5 March 58)

DIST: 3 - KUCLUB ✓
3 - File

~~SECRET~~

CONFIDENTIAL